OTXOF 8.4.1.1 v.1

Altino Properties, Inc.

Documents Produced to the
U.S. Environmental Protection Agency
On April 24, 2008
Pursuant to the 104(e) Request

Washington State Department of Ecology's records for the BNRR Quendall Loading Rack Site



Renton, K.

N-17-5626-000
N501608
SEE ALSOL
QUENDALL TERMINALS
1996 - 1998

12/22/98

8:54 AM INCIDENT ID: X501608

DEPARTMENT OF ECOLOGY ENVIRONMENTAL REPORT TRACKING SYSTEM

REFERRAL

PROGRAM/ORGANIZATION: TOXICS CLEANUP

CONTACT: SECTION HEAD

REFERRAL DATE: 12/21/1998

URGENT RESPONSE?: N PRIMARY?: Y

REPORT 1 OF 1

PAGE 1

OTHER PROGRAM/ORGANIZATIONS REFERRED TO:

ADDITIONAL INFO:

COORDINATOR: HOVIK, DAVID

DATE/TIME REC'D: 12/21/1998 12:00 PM REPORT TYPE: INITIAL

ACTUAL DATE: 12/21/1998

CALLER NAME: COLBURN, GAIL ANONYMOUS?: N

ADDRESS:

CONTACT 1:

EXT: PHONE: W (b) (6) TYPE:

COUNTY: KING

CITY: RENTON

WEATHER:

TIDE:

WATERWAY:

LATITUDE:

LONGITUDE:

TOWNSHIP:

RANGE: E/W: SECTION:

LOCATION INFO: RR RIGHT OF WAY ADJACENT TO 4305 LAKE WA BLVD; E OF TRACK AND W

OF BLVD

MEDIUM: GROUND WATER

MATERIAL: OTHER HAZARDOUS QTY: 0 UNIT: HAZARDOUS: Y

CAUSE: OTHER

12/22/98 8:54 AM DEPARTMENT OF ECOLOGY ENVIRONMENTAL REPORT TRACKING SYSTEM

INCIDENT ID: N501608

REFERRAL

IMPACT: GROUND WATER CONTAMINATION

SOURCE: TRANSPORTATION-RAIL

ACTIVITY: TRANSFERRING

ALLEGED VIOLATOR 1: BNSFRR - QUENDALL LOADING DOCL

ADDRESS: RR RIGHT OF WAY ADJ TO LAKE WA BLVD

RENTON WA

ADDITIONAL INFO:

ADDITIONAL INFORMATION ON INCIDENT:

II COMPLETED BY GC IN 97. HISTORIC FORMER LOADING RACK FROM QUENDALL TERMIANLS, LOCATED E OF RR TRACKS, W OF LAKE WA BLVD ON BNSF RR RIGHT OF WAY. SIS LIST SUSP FOR PAH, VOA, BNA, BASED ON HISTORIC INFO ON PAST PRACTICES.

PAGE 2

Colburn, Gail

From: Colburn, Gail

Sent: Friday, August 31, 2001 1:38 PM

To: Sato, Brian

Cc: Alexander, Steve (ECY); Wietfeld, John

Subject: FW: SHA sites

F.Y.I.

----Original Message-----From: Colburn, Gail

Sent: Friday, August 31, 2001 1:37 PM

To: 'Thomsen, Carsten' Subject: RE: SHA sites

The site has never been sampled. The listing was done based on prior Ecology knowledge with facilities of this nature and knowing the operational history of the facility, based on anecdotal information obtained during an interview with the former plant manager for the old, adjacent Reilly Tar and Chemical Facility (now Quendall Terminals site, ranked #1 and severely contaminated.) The contamination could include both floating and sinking product (PAHs and VOAs), is all subsurface and drilling and/or test pits and sampling (including groundwater quality assessment) needs to be done at the site to assess the nature and extent of contamination. Until this is done (by someone), it is a poor candidate for an SHA, due to the lack of data, and should remain listed as suspected on the contaminated sites list. Thanks for asking, Gail
——Original Message——

From: Thomsen, Carsten [mailto:Carsten.Thomsen@METROKC.GOV]

Sent: Thursday, August 30, 2001 7:31 AM

To: Colburn, Gail Subject: SHA sites

Hey Gail,

Yolanda and I were over at NWRO the other day looking at files for possible new SHA sites. One of the sites I was looking at was BNRR Quendall Loading Racks. Sally said that you sent her a message saying that it needed a site assessment so it should not be done as an SHA????? Could you clarify that for me so we know what to do with the site in the future? Thank you.

Carsten

DEPARTMENT OF ECOLOGY **TOXICS CLEANUP PROGRAM** SITE DATA SUMMARY as of 12/31/98

FACILITY SITE ID: 61436398

SITE NAME: BNRR QUENDALL LOADING RACKS F

TCP ID: N-17-5626-000

SITE LOCATION INFORMATION

ADDRESS: E OF RR TRACKS & 4503 LK WASHIN

DEGREES MINUTES SECONDS 12

31

TOWNSHIP RANGE SECTION

LATITUDE:

122

3.01

0

CITY: RENTON

LONGITUDE:

47

50.6

LEGISLATIVE DISTRICT #:

ZIP CODE: 98055 COUNTY: KING

TAX PARCEL #:

CONGRESSIONAL DISTRICT #:

SITE STATUS INFORMATION

ECOLOGY STATUS: 1 Awaiting SHA

WARM BIN #:

INDEPENDENT STATUS:

STATUTE: 2 MTCA only

PROGRAM PLAN:

ERTS ID: N501608

LUST ID:

RESPONSIBLE UNIT: NORTHWEST

PROJECT CODE:

SITE MANAGER: COLBURN, GAIL

ENTERED DATE: 12/31/98

NFA CODE:

SITE UPDATE DATE: 1/1/53

NFA DATE:

SITE COMMENTS

Former Quendall Terminals loading rack. Site listed based on historic information of past practices. Potential soil contamination by PAHs, VOAs & BNAs.

AFFECTED MEDIA AND CONTAMINANTS INFORMATION

MEDIA	STATUS	#1	#2	<u>#3</u>	#4	<u>#5</u>	<u>#6</u>	#7	#8	#9	<u>#10</u>	#11	<u>#12</u>	<u>#13</u>	#14	<u>#15</u>	<u>#16</u>	#17 DW 7	YPE:	-
1 Groundwater	s	s					·			S		s								
4 Soil	s	s								S		S						·		

AFFECTED MEDIA AND CONTAMINANTS LEGEND

#1 = Base/Neutral Organics

#2 = Halogenated Organic Compounds

#3 = Metals-Priority Pollutants

#4 = Metals-Other

#5 = PCB #6 = Pesticides #7 = Petroleum Products

#8 = Phenolic Compounds

#9 = Non-Halogenated Solvents

#10 = Dioxins

#11 = PAH

#12 = Reactive Wastes

#13 = Corrosive Wastes

#14 = Radioactive Wastes

#15 = Conventional Contaminants, Organic

#16 = Conventional Contaminants, Inorganic

#17 = Asbestos

12/22/98 8:54 AM

DEPARTMENT OF ECOLOGY

INCIDENT ID: M501608

ENVIRONMENTAL REPORT TRACKING SYSTEM REFERRAL

INVESTIGATOR: J. J. William
DATE STARTED:// DATE COMPLETED: \(\lambda \frac{1}{2} \rac{1}{2} \rac{1}{9} \rightarrow \)
ACTION: Chille investigation ACTION DATE: 5/1/97
NARRATIVE:
S'te won BNRR Right of Way, F. of tracks, W. of hake
A CONTINUE OF TAMES AND
William (Short on Will Proposity)
updated IITS 13/23/98 cut wife of point practices,
1 1 0 16 0 H 05 1 1 - 5626-000

IF DOCUMENT WAS RECEIVED: INTERIM FINAL WASTE MANAGEMENT PRACTICE:	_ Lust	SIS DATE RECEIVED
DOCUMENT TITLE:		and the second second second
NOTE: If an ERTS report already exists, fill out only those areas		
and the things that it is an in the course of the sea green of the whole the property of the course of the continue of the course of the cours	Andrews of the second	
* REPORT # / MENVIRONMENTAL REPO	RTS TRA	CKING SYSTEM
Recorder: Date: 12/2/198	Time:	Incident Date:
ANONYMOUS Time of Return Call:		ERTS Number: <u>N5 0160 8</u>
*Reported By:	Bı	usiness:
*Address:		
*City: State: Z	ip:	Best Time to Return Call:
Home Phone: Work Phone:		Phone Type:
*COUNTY Line CITY Routon	SMAPTHE VILLE	Weather:
Waterway:	Type:	
Location of Incident: RR NING & Word al		33 Kake Wash Dlud
For the start of the	of R lug)
	1	Made Chillips (1966) Chillips (1967)
*Medium: 10 /241 *Material: often hours	AJOil/Pet	roleum:
The contract of C^{\prime} , which is the contract of G	Section 1	Unit of Measure:
Providence and the state of the	Date of the control of the	ils groundinate unitari
and the profit of the profit o	1 - 1	And the late of the contract o
ing in initial and was Massack and the Allerman and Allerman and in the Allerman in the Allerman and the All	trænsfl	en in A legation in targetten solland bestieden der titelt in der titel
Human Factor: Vessel Type:		Vessel Name:
*Alleged Violator (AV) BNRR / (Villaged)	Millar	harman land
	<u>x poden</u>	
*AV Address: KK right of way and to	4503	KERE WASH (RUND)
*City: Koulon 0 State: Wa.	Zip + 4:	
Contact: Phone:		Type: Ext.:
*Incident Details As Reported:		
XX Como litta lu QO m'97, 1	Vistoria.	Dormor landing rades
la son Bud and all of a rain and in los	tool I	LOS PR TRANSPORT 10 OF
A sko mal Rand on Q NOR	Right	A May O'Y Chirt
MILLO DOS PHHA DAHA RAJA	1 /10	100 an Viitoria into on
part practicle.	- Gara	and the second



STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

Northwest Regional Office, 3190 - 160th Ave S.E. • Bellevue, Washington 98008-5452 • (425) 649-7000

January 4, 1998

<u>CERTIFIED MAIL</u> Z 337 937 175

Mr. Alex Cugini
Altino Properties
c/o Barbee Mill Co., Inc.
P.O. Box 359
Renton, WA 98057

Dear Mr. Cugini:

Re: EARLY NOTICE LETTER #N-17-5626-000

BNRR Quendall Terminals Loading Rack (Former)

E of RR Tracks & W of 4503 Lk Washington Blvd N, Renton, WA

This letter is sent to you concerning information that the Department of Ecology (Ecology) has gathered regarding the above referenced property. As part of the process under the Model Toxics Control Act (MTCA), Ecology maintains a list of known or suspected contaminated sites. Based on available information in the department's files, it is Ecology's decision to add this property to the list as a site suspected to be contaminated by hazardous substances.

Enclosed is a data summary report containing information we believe reflects the current site status. A legend is also enclosed to help interpret codes used in this report.

Please note that inclusion on the list does not mean that Ecology has determined you to be a potentially liable person responsible for cleanup under the MTCA. However, this letter is a notification that an area(s) of contamination may exist on this property. Further investigation or cleanup action will need to be done to comply with Washington State laws and regulations.

Because of considerable potential liability, please be advised to carefully consider any investigation or cleanup actions and to carefully document steps taken independent of Ecology's involvement. Guidance documents to help conduct an independent cleanup are available if you are interested in this option. In proceeding with an independent cleanup, please be aware there are requirements in State law that must be met. Some

Mr. Alex Cugini January 4, 1999 Page 2

of these requirements are addressed in WAC 173-340-120(8)(B) and -300(4). Ecology will use the appropriate requirements contained throughout this chapter in its evaluation of the adequacy of any independent remedial (cleanup) actions performed. Ecology has a strong commitment to work cooperatively with individuals to accomplish prompt and effective investigations and site cleanups. However, due to limited resources and requirements in State law, we are not able to provide all the assistance requested. Your cooperation in planning or conducting a cleanup action is not an admission of guilt or liability.

If an independent cleanup action is undertaken, and a formal review of the work is desired, a report may be submitted to Ecology through the Voluntary Cleanup Program. This program was established in response to the public's need for Ecology to more rapidly review cleanup actions. A fee has been established to support this review process. Guidance documents to help conduct an independent cleanup are available if you are interested in this option.

If a cleanup action is undertaken and a formal review of the work is not desired at this time, then the information should be submitted to Ecology in order to document any assessment or cleanup activities. If no report is available, but work is in progress or anticipated, a letter describing these plans would be helpful in updating the site record.

If an independent cleanup action does not occur on this property, Ecology will conduct a more detailed inspection at a future time that may include testing for contamination. After that, Ecology will assess what action is needed and establish a priority for that work under the formal MTCA cleanup process. At that time, the potentially liable person(s) would be determined and would be responsible for cleanup costs, including State oversight.

Should you have any questions regarding this letter or if you would like a copy of Chapter 70.105D RCW (The Model Toxics Control Act), the implementing regulations, Chapter 173-340 WAC, that detail these requirements, or a guidance document, please contact me at (425) 649-7058. Thank you in advance for your cooperation. and the constant of the control of t

The first of the second of the

Sincerely, Jail Collum

Gail Colburn
Aquatics Unit Supervisor
Toxics Cleanup Program

GCC:lb

Enclosures: 2

Distribution List: Burlington Northern Santa Fe Railroad, 2454 Occidental Ave. S., Seattle, WA 98134 Georgia Baxter, J H Baxter & Co., PO Box 5902, San Mateo, CA 94402



STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

Northwest Regional Office, 3190 - 160th Ave S.E. • Bellevue, Washington 98008-5452 • (425) 649-7000

January 4, 1998

<u>CERTIFIED MAIL</u> Z 337 937 172

Ms. Georgia Baxter
J H Baxter & Co.
1700 S. El Camino Real
P.O. Box 5902
San Mateo, CA 94402-0902

Dear Ms. Baxter:

Re: EARLY NOTICE LETTER #N-17-5626-000

BNRR Quendall Terminals Loading Rack (Former)

E of RR Tracks & W of 4503 Lk Washington Blvd N, Renton, WA

This letter is sent to you concerning information that the Department of Ecology (Ecology) has gathered regarding the above referenced property. As part of the process under the Model Toxics Control Act (MTCA), Ecology maintains a list of known or suspected contaminated sites. Based on available information in the department's files, it is Ecology's decision to add this property to the list as a site suspected to be

contaminated by hazardous substances.

Enclosed is a data summary report containing information we believe reflects the current site status. A legend is also enclosed to help interpret codes used in this report.

Please note that inclusion on the list does not mean that Ecology has determined you to be a potentially liable person responsible for cleanup under the MTCA. However, this letter is a notification that an area(s) of contamination may exist on this property. Further investigation or cleanup action will need to be done to comply with Washington State laws and regulations.

Because of considerable potential liability, please be advised to carefully consider any investigation or cleanup actions and to carefully document steps taken independent of Ecology's involvement. Guidance documents to help conduct an independent cleanup are available if you are interested in this option. In proceeding with an independent cleanup, please be aware there are requirements in State law that must be met. Some

Ms. Georgia Baxter January 4, 1999 Page 2

of these requirements are addressed in WAC 173-340-120(8)(B) and -300(4). Ecology will use the appropriate requirements contained throughout this chapter in its evaluation of the adequacy of any independent remedial (cleanup) actions performed. Ecology has a strong commitment to work cooperatively with individuals to accomplish prompt and effective investigations and site cleanups. However, due to limited resources and requirements in State law, we are not able to provide all the assistance requested. Your cooperation in planning or conducting a cleanup action is not an admission of guilt or liability.

If an independent cleanup action is undertaken, and a formal review of the work is desired, a report may be submitted to Ecology through the Voluntary Cleanup Program. This program was established in response to the public's need for Ecology to more rapidly review cleanup actions. A fee has been established to support this review process. Guidance documents to help conduct an independent cleanup are available if you are interested in this option.

If a cleanup action is undertaken and a formal review of the work is not desired at this time, then the information should be submitted to Ecology in order to document any assessment or cleanup activities. If no report is available, but work is in progress or anticipated, a letter describing these plans would be helpful in updating the site record.

If an independent cleanup action does not occur on this property, Ecology will conduct a more detailed inspection at a future time that may include testing for contamination. After that, Ecology will assess what action is needed and establish a priority for that work under the formal MTCA cleanup process. At that time, the potentially liable person(s) would be determined and would be responsible for cleanup costs, including State oversight.

Should you have any questions regarding this letter or if you would like a copy of Chapter 70.105D RCW (The Model Toxics Control Act), the implementing regulations, Chapter 173-340 WAC, that detail these requirements, or a guidance document, please contact me at (425) 649-7058. Thank you in advance for your cooperation.

化油油 医乳腺性 电电流电流 化二甲基甲酚二烷 医甲状腺病

and the state of t

Sail Collura
Gail Colburn
Aquatics Unit Supervisor Toxics Cleanup Program

GCC:lb

Distribution List:

Enclosures: 2

Distribution List: Burlington Northern Santa Fe Railroad, 2454 Occidental Ave. S., Seattle, WA 98134 Altino Properties c/o Barbee Mills Co., Inc., Alex Cugini, PO Box 359, Renton, WA



STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

Northwest Regional Office, 3190 - 160th Ave S.E. • Bellevue, Washington 98008-5452 • (425) 649-7000

January 4, 1998

<u>CERTIFIED MAIL</u> Z 337 937 173

Burlington Northern Santa Fe Railroad 2454 Occidental Avenue S. Seattle, WA 98134-1451

Dear Sir or Madam:

Re: EARLY NOTICE LETTER #N-17-5626-000

BNRR Quendall Terminals Loading Rack (Former)

E of RR Tracks & W of 4503 Lk Washington Blvd N, Renton, WA

This letter is sent to you concerning information that the Department of Ecology (Ecology) has gathered regarding the above referenced property. As part of the process under the Model Toxics Control Act (MTCA), Ecology maintains a list of known or suspected contaminated sites. Based on available information in the department's files, it is Ecology's decision to add this property to the list as a site suspected to be contaminated by hazardous substances.

Enclosed is a data summary report containing information we believe reflects the current site status. A legend is also enclosed to help interpret codes used in this report.

Please note that inclusion on the list does not mean that Ecology has determined you to be a potentially liable person responsible for cleanup under the MTCA. However, this letter is a notification that an area(s) of contamination may exist on this property. Further investigation or cleanup action will need to be done to comply with Washington State laws and regulations.

Because of considerable potential liability, please be advised to carefully consider any investigation or cleanup actions and to carefully document steps taken independent of Ecology's involvement. Guidance documents to help conduct an independent cleanup are available if you are interested in this option. In proceeding with an independent cleanup, please be aware there are requirements in State law that must be met. Some of these requirements are addressed in WAC 173-340-120(8)(B) and -300(4). Ecology will use the appropriate requirements contained throughout this chapter in its

Burlington Northern Luita Fe Railroad January 4, 1999 Page 2

evaluation of the adequacy of any independent remedial (cleanup) actions performed. Ecology has a strong commitment to work cooperatively with individuals to accomplish prompt and effective investigations and site cleanups. However, due to limited resources and requirements in State law, we are not able to provide all the assistance requested. Your cooperation in planning or conducting a cleanup action is not an admission of guilt or liability.

If an independent cleanup action is undertaken, and a formal review of the work is desired, a report may be submitted to Ecology through the Voluntary Cleanup Program. This program was established in response to the public's need for Ecology to more rapidly review cleanup actions. A fee has been established to support this review process. Guidance documents to help conduct an independent cleanup are available if you are interested in this option.

If a cleanup action is undertaken and a formal review of the work is not desired at this time, then the information should be submitted to Ecology in order to document any assessment or cleanup activities. If no report is available, but work is in progress or anticipated, a letter describing these plans would be helpful in updating the site record.

If an independent cleanup action does not occur on this property, Ecology will conduct a more detailed inspection at a future time that may include testing for contamination. After that, Ecology will assess what action is needed and establish a priority for that work under the formal MTCA cleanup process. At that time, the potentially liable person(s) would be determined and would be responsible for cleanup costs, including ate oversight. State oversight.

Should you have any questions regarding this letter or if you would like a copy of Chapter 70.105D RCW (The Model Toxics Control Act), the implementing regulations, Chapter 173-340 WAC, that detail these requirements, or a guidance document, please contact me at (425) 649-7058. Thank you in advance for your cooperation.

Sincerely,

Sail Collurn

Gail Colburn

Aquatics Unit Supervisor

Theorem Program Toxics Cleanup Program

GCC:lb

GCC:lb

Enclosures: 2

Distribution List:

Ms. Georgia Baxter, JH Baxter & Co., P.O. Box 5902, San Mateo, CA 94402 Altino Properties c/o Barbee Mills Co., Inc., Alex Cugini, PO Box 359, Renton, WA 98057

	FACILITY SITE INFO	RMATION (TCP)
Site Name: BV 6	R/Quendall Long	ding Rocks EPAID:
Location Descriptio	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Land hake Wash Blod.
	outside property l	Soundary Quendall Terminals
Geographic Position	01 = Centrold of STR Unit D: 02 = Centrold of STR Otr, Sec	07 = NW Corner of Land Parcel: ction 08 = Plant Entrance
	03 = Centroid of STR QTR QT 04 = Centroid of STR QTR QT 05 = Facility/Sile Centroid	TR Section 09 = SE Corner of Land Parcel
an an	06 = NE Comer of Land Parce	
Site Address PR	Kight of four wash	B. Opal.
city Routo	<u>~</u>	Zip:
County Lin	WRIA ID): Indian Land: 🏻
	01 = Not Applicable 07 = *1:82,500	13 =*1:10,000
Collection Source:	02 = "1:500,000	14 = 1112,000 20 = 115,001-110,000 15 = 1125,001-1:50,000 21 = 115,001-1:5,000
	04 = *1:125,000	16 = 1:50,001-1:100,000 22 = <=1:500 17 = 1:20,001-1:125,000 23 = <1:500 18 = 1:15,001-1:20,000 99 = Unknown
,	01 = Address Matching—Block Face 02 = Address Matching—House Numb	
	03 = Address Matching—Street Center 04 = Address Matching—Unknown 05 = Aerial Photography—Rectified	rline 18 = GP\$ (Unknown) 19 = Hand Measured—paper map 20 = EORAN-C
Collection Method:	06 = Aerial Photography—Unknown 07 = Aerial Photography—Unreclified 08 = Cadastral Survey	21 = Orthophotography—digital 22 = Orthophotography—paper 23 = Satellite Imagery—Landsat MSS
—	Q9 = Census Block 1990 Centrold 10 = Census Block Group 1990 Centro 11 = Conversion from STR	24 = Satellite Imagery—Landsat TM
	12 = Digital or manual raw photo extract 13 = Digitized of CTR screen/digital dat	tion 27 = Satellite Imagery—SPOT Multi Spectral
	14 = Digitized—paper map 15 = GPS (Carrier/Geodetic)	59 ÷ Orintown
Horizontal Datum:	01 = North American Datum 1927-NAD2 02 = North American Datum 1983 ('91 ac	
<u></u>	03 = HARNI D4 = WGS84 (GPS NAVD88) 99 = Unknown	
_	01 = Large Facility/Complex or area > 1	O Acre
Areal Extent Code:	02 = Small Facility/Complex or area > 1 03 = Large Building or area > 5,000 sq.	Acre < 10 Acre: ft:
	04 = Small Building or area < 5,000 sq 05 = Crossing or intersection of two feat 06 = Small object or area < 10 sq. ft., e	itures; e.g., bridge stream
	§ 99:= Unknown	
Accuracy Level:	01 = > 1/100 meter 02 = < 1/10 meter and > 1/100 meter 03 = < 1 meter and > 1/10 meter	06 = +/- 40 feet (12 meter) 11 = +/- 1000 feet 07 = +/- 100 feet (35 meter) 12 = +/- 2000 feet 08 = +/- 180 feet (55 meter) 13 = > 2000 feet
	04 = +/- 10 feet (3 meter) 05 = +/- 20 feet (6 meter)	09 = 4/- 250 feet 99 = Ûnknown⊗ 10 = +/- 500 feet

)[4]4]98

		<u> </u>						
	Degrees	Minutes	Seconds		Number	Directio		Circle ane
Latitude:	47	31		ection:			Sec 1	SW SE
Longitude:	122	12	<u>3.01</u> 1	ownship;			Sec 2	NW NE SW SE
If you don't ha	ve LAT/LONG,	please provide ma	p of site!	lange:	.		Sec 3	NW NE SW SE
Ecology In	teraction (check all that	anoly)	9775	tem:		•	
_			•	/	<i>j</i>			
∐ FC		• •	fund Cleanup Site)		SIS	· •.		
LU LU:		LUST Facility			UST/LU	ST		
□ sc		State Cleanup						•
U vo	LCLNST	Voluntary Cle	anup Site					
Active Stat	tus:	_ Date: _	· · · · · · · · · · · · · · · · · · ·	Inactiv	e Status:		Date: 12/	131/98
Sic Code:	Descrip	otion:						· · · · · · · · · · · · · · · · · · ·
1.	Barre	a. And	ارنیم میآ	0 4	· · · · · · · · · · · · · · · · · · ·			
2.	1 form	UN JAGOR	ing rank		· · ·	:	<u> </u>	
If this site is	a sub-site or	operable uni	of a larger sit	e, include th	ie name an	d FS ID#	of the pare	nt site:
FS ID#:			Site Nam	e:				
				· · · · · · · · · · · · · · · · · · ·				
Company I	Vame;	Burlingte		m Rail	road	Title:	MR MS	
Last Name		· · · · · ·	First Na			Mi	ddle Initia	i:
Address:	245	4 Occi	dental	Ave S.		_ PO E	3ox:	
City: Se	atte	SI	ate: NA	Zip: _	98/34-1	451	Country:	 .
Tax ID#:		UBI#:		Pho	ne#;	· · · · · · · · · · · · · · · · · · ·	Ext:	
Fax#:		_ Alt Phone	e#:	E	-Mail Add	dress:		,
	AC = Ad	plication: Contact	DBA = Doing	Business As		PE = Projec	t Engineer	
Relationsh Code:	ID AGT = A AP = Aff	gent ected Party		mer Operator		Pl = Public PLP = Pote	Involvement Pe ntially Liable Pe	rson rsca
	ATT#A	Applicant ttorney Ing Contact	FOWNR = Fo FT = Former HWT = Hezy	itmer Owner Haz Waste Tra Väste Transpoi	nsporter l	PM = Projec PRMT = Pe PRP = Pote		sible Party
LPO	BO = Bu CA = Co	siness Owner Applicant	IC = Inspection LAO = Land C	n Contact Wner		SA = Site A SC = Site C	ttorney ontact	
	CNTR =	rrent Generator Contractor ost Recovery Par	LEO = Legal (MH = Mortgag ty OP = Operato	e Holder	` <u>`</u>	SO = Site C 「SC = Toxio JNK = Unki	cs Site Contact	
Relationshi				Relations			· · · · · · · · · · · · · · · · · · ·	·

sel mailing address info under Quendall Terminal

·				·	91	William !	Juny
		· · · · · · · · · · · · · · · · · · ·	Party I	nformation			
	ndividual Details		·		/	<u>,</u>	·
Party Type: (Check one)	_	Company Name:	() Is On a	bell Ten	על לא מונינו		
·	· · · · · · · · · · · · · · · · · · ·	Individual's				†	
Compa	ny	Last Name:	4503	LK. Wash. ton, 98056-	Blud. N.	Title:	
Individu	ıal	First Name:	Ken	ton, 98056-	1609	M.I.:	
1		,				Phone	
Tax ID#:		UBI#:	•	Phone #:		Ext. #:	
-		E-Mail					
Fax#:		Addressi:				Alt Phone #:	•
Party Affiliation	Maintenance:	A CELICATION .				,	
(Name of	Co. that an indivi	Affiliation: dual represents)	•			Start Date:	
Relationship	レんピノ	Relationship					
Code:	FORER	Description:	·——·			End Date:	
Mailing Address				 			
Address:	POBO	x 5902	<u> </u>		·		·····
	<u> </u>					PO Box:	-
City:	Lewn	inteo	State CA	Zip Code:	94402	Country:	
			Party (r	nformation			
3) Company/Ir	dividual Details	 	, arty ii	nomation.			<u> </u>
Party Type:		Company					
Check one)		Name:	·			ļ	
Compa	nv l	Individual's Last Name:		•		Title:	
Compa	<u>'''</u>	Last Maine.				ride.	
Individu	al	First Name:				M.I.:	
						Phone	
Tax ID#:		UBI#:		Phone #:	<u> </u>	Ext. #:	·
Fax#:		E-Mail Addressl:				Alt Phone #:	
arty Affiliation N	Aaintenance:		-				
		Affiliation:					
	Co. that an individ	lual represents)				Start Date:	
Relationship	•	Relationship					
Code:		Description:				End Date:	·····
lailing Address:	······································	· · · · · · · · · · · · · · · · · · ·				1	
Address:				·			·
	·	•				PO Box:	٠.

Country:


State

City:

Zip Code:

SIS INFORMATION SIS INFORMATION
Site Name: BNRR/Quendall Localing Rasks FSID: 61436398
TCP ID: N-11-5626-000 Tax Parcel #: UBAT: UBAT: Warm Bin #:
Ecology 1 = Awaiting SHA 5 = Construction Completed; 0 & M Underway Status: 2 = Ranked, Awaiting RA 6 = RA Completed; Confirmational Monitoring Underway 3 = RA in progress 7 = RA Conducted; residual contamination [eff on site; on-going institutional controls required. 4 = Independent RA 8 = RA and other activities completed
Statute: 1 = CERCLA 2 = MTCA Only 3 = RCW 70.105B 4 = RCW 90.48 5 = RCRA-C 6 = RCRA-D 7 = MTCA (SED) Independent 5 = Release report received, awaiting assessment by PLP 5 tatus: 2 = Independent Site Assessment or Interim RA Report received 3 = Independent Final RA Report received This field is required if Ecology Status is 4)
Program Plan: 1 = Prepayment 2 = Program Plan 3 = IRAP Owner Type: t = Private 5 = State 9 = Unknown 2 = Municipal 6 = Tribal 10 = Publicly-Owned (Bankrupt) 3 = County 7 = Mixed 11 = Financial Institution Owned (Bankrupt) 4 = Federal 8 = Other
NFA 1 = NFA after assessment (or IRAP) 2 = Removed from Hazardous Sites List (HSL) 3 = Referred (transferred to another Ecology Prog. 4 = Referred to another agency 5 = Referred to local governmental entity 6 = Cleaned up under prior authority 7 = Cleanup completed; not on HSL Date:
ERTS ID: 501608 LUST ID: AFRS Code:
Site Comments:
Activity Activity Start End Activity Action Neg. Lega Code Status Date Date Lead By Start Date Mech
Activity SD = Site Discovery EA = Emergency Action CC = Cleanup Construction Codes: II = Initial Investigation
Activity Status Codes: C=Completed S=In Process P=Planned Codes: Codes: Codes: C=Completed S=Ecology Contractor Action By S=Ecology
Activity Comments:

	-																	. 1
Media	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	
1 Groundwater	S			·					S		S							
2 Surface Water															:			D W
3 Air									·									
4 Soil	S								5		5							T
5 Sediment															·			P E
6 Drinking Water															. ,			-
· .				1:						90801.647.	Landa Viet	1 100 2 10	0700.00.00000		1	1	******	
t = Base/Neutral Organics 7 = Petroleum Products 13 = Corrosive Wastes 2 = Halogenated Organic Compounds 8 = Phenolic Compounds 14 = Radioactive Wastes 3 = Metals—Priority Pollutants 9 = Non-Halogenated Solvents 15 = Conventional Contaminants; Organic 4 = Metals—Other 10 = Dioxins 16 = Conventional Contaminants; Inorganic 5 = PGB 11 = PAH 17 = Asbestos 6 = Pesticides 12 = Reactive Wastes																		
Status B = Below Codes: R = Remed	Cleanup										Dri	nking Typ	y Wa es:	iter	2 =	Single Comm	`aXX .XXX.	
IRAP Review Resu	lts:					levie\					·	Tot	al Ho	ours:	·			
Cleanup Conducted: F									RAP nmer	nt:					,			
Check ☐ 1. Drug Lab ☐ 5. Landfill ☐ 9. Spill ☐ 2. Drum ☐ 6. Land Application ☐ 10. Storm Drain ☐ 3. Impoundment ☐ 7. Pesticide Application ☐ 11. Tank ☐ 4. Improper Handling ☐ 8. Pesticide Disposal ☐ 12. Unknown																		
Alternate Site Names:																		
1. former Quendall Verninals Loading Rack																		
2.								•	0						origa -	- <u></u> -		
	· · ·									- ;			·	* .				





FAX COVER SHEET

1011 S.W. Klickitet Wo Suite 207 Septile, WA 98134 (206) 624-9349

Date: 10/3/76

Total Pages: 3

Task Number: 3-2438 - 323 :

Message: Please call if this is not what you need

	Fax Sent to:	Fax#	Speed Dial #
	Jeff Graves - JAG	453-1985	6
	Bob Collier - JAG	453-1985	6
	Chuck Wolfe - Foster Pepper & Sheffelman	447-9700	9
	Joe Delaney - Foster Pepper & Sheffelman	447-9700	9
	Larry Martin - Foster Pepper & Sheffelman	455-5487	60
	Ron Leibsohn - Leibsohn & Company	455-2196	65
	Don Stark - Goggerty & Stark	292-2063	67
	Jim Spitze - CNA Architecture	828-9116	34
	Arlan Collins - CNA Architecture	828-9116	34
(XX	Gail Colbum - Dept. of Ecology	649-7098	30
	Brian Sato - Dept. of Ecology	649-7098	30
	Ching-Pi Wang - Dept. of Ecology	649-7098	30
	Tanya Barnett - Assistant Attorney General	438-7743	61
	Jana Huerter - City of Renton	235-2541	62
	James Hanken - Schwabe Williamson	292-0460	36
	Lynn Manolopoulos - Davis Wright	646-6199	<i>5</i> 0
	Robert Cugini - Barbee Mills	271-8844	68
	Jennifer Henning - City of Renton	277-4455	63
	Georgia Baxter - J.H. Baxter & Company	(415) 570-6878	64
	Lawrence Warren - Warren, Kellogg, Barber	255-5474	66 ~
	OTHER_		<u>.</u>


PLEASE CALL (206) 624-9349 IF YOU HAVE ANY TROUBLE RECEIVING THIS FAX.


JAG.FAX


REMEDIATION TECHNOLOGIES INCORPORATED OFFICES NATIONWIDE

9/23/96









000483

BNRR/QUENDALL LOADING RACKS

Thu Dec 31 11:53:17 1998

47° 31′ 50.60″ 122 12 3.01 122

Scale 1:7,812 (at center)

200 Meters

Population Center

□ Geo Feature

Interstate, Turnpike

Street, Road

- Hwy Ramps

__ Major Street/Road

____ Interstate Highway

++++ Railroad

... River

Open Water